

INSPECTION REPORT

DATE:

NAME:

LOCATION:

¼ ¼:

SECTION:

PARCEL ID#

TOWNSHIP: Springdale

ZONING DISTRICT:

RE: Navigability determination

REPORT:

Defined slopes and ditch
Slopes are greater than 12%
No current erosion (no destruction or prevention of terrestrial vegetation).
No surface water present.
Partly cloudy and cold (dry conditions)

Based upon walking north and south of the property there is a clear definitive bed and bank.
It is my opinion that this is a navigable intermittent stream.

PHOTOS: see attached

ZONING INSPECTOR: Daniel Everson

TIME:



looking north at the start of tributary



looking south along bottom of slope



bottom of slope



bottom of slope looking south



looking north along bottom of slope



looking north along easterly property line

